Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080129-1

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY
2961 E. COLORADO ST., PASADENA, CALIF.

No. 11141

RECEIVED FROM PLANT #2

DATE REC'D 2-3-57
P.O. NO.
VENDOR PACKING SLIP NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO. / S.O. NO.
	322	0C0000	20018	0	0	00	00			

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
6	738210 Shaft Gear Belt	6 ✓		
	[illegible] MT. 85-13	1		

RECEIVED BY

INSPECTED BY Dewa DATE 2/1/57

REJECTS RETURNED ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY
2961 E. COLORADO ST., PASADENA, CALIF.

No. 11148

RECEIVED FROM PLANT #2

DATE REC'D 2-3-57
P.O. NO.
VENDOR PACKING SLIP NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO. / S.O. NO.
	322	0C0000	20020	0	0	00	00			

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
22	738214 Bearing Bracket Assly	22 ✓		

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080129-1

RECEIVED BY

INSPECTED BY Dewa DATE 2/2/57

REJECTS RETURNED ON SHIP. MEMO NO.

HMC-108s